

SPECIALTY CELLULAR – BOTTOM UP/TOP DOWN BILLOWS WHEN TOP DOWN PORTION IS LOWERED



Possible Cause:

1. The Bottom rail is resting on the sill.

Solution:

1. Raise the bottom rail 1/16" off the sill, then try lowering again.